

F16.1

Source Image 18.

Output Inroge 14)

Sverigit 30

FIB. 2A

F16. 28

	Chedwan Marker	
Heec .		Blank Checko Mach Mach Mach Stop Stop Stop Stop (Stop
owo V	Information Morling and	Blank Check5 Mach Mach Stop Stop
	Informa	Typest Check4 Mach Mach Mach Blank Blank
. Արայի, Արայի, Արայի	Lowerbor (Start Char)	Type3 Check3 Mach Mach Mach Blank Blank
		Type2 Check2 Mach Mach Mach Blank Blank
		Type I Check I Mach Mach Blank Blank
		Start Blank Mach Mach Blank Blank Blank
) more way	Start Start Start Star Mach Mach Mach Mach Mach Mach Mach Mach
	Local	
		Information Monter Add

Definitions:

Start/Stop = Common repeated patterns in each matrix

TypeX = Machine type identifier CheckX = Checksum bits Mach = Machine serial number encoding cells

F19.W





FIG. 5



!>



